

## 2014 OCCUPANTS IN INJURY CRASHES WITH SEAT POSITION / INJURY STATUS

	Incap	Non-Incap	Possible	No Injury	Unknown	Total
Bus Passenger	0	9	0	0	0	9
Driver	281	1116	1141	1739	96	4373
Fourth Row Left	1	1	0	1	0	3
Fourth Row Middle	1	2	0	0	0	3
Fourth Row Right	1	1	0	2	0	4
Front Row Middle	0	5	5	18	1	29
Front Row Right	55	264	309	525	23	1176
Lying Down Front Seat	0	0	0	1	0	1
Lying Down Other Seat	1	4	1	1	0	7
Motorcycle Passenger	8	25	7	7	1	48
Other (explain in narrative)	0	2	5	3	0	10
Other Enclosed Area	1	6	3	2	0	12
Other Row (i.e. Bus, Van)	0	0	1	1	3	5
Passenger Front Row Left (Vehi	0	2	6	9	0	17
Second Row Left	11	37	49	194	9	300
Second Row Middle	5	13	26	74	3	121
Second Row Right	15	60	70	235	9	389
Sleeper Section of Cab	3	11	8	19	0	41
Third Row Left	0	5	4	21	1	31
Third Row Middle	1	3	1	13	0	18
Third Row Right	0	5	4	20	0	29
Trailing Unit	2	3	0	3	0	8
Unenclosed Cargo Area	0	0	0	3	0	3
Unknown (explain in narrative)	26	3	14	150	9	202
<b>Total</b>	<b>412</b>	<b>1577</b>	<b>1654</b>	<b>3041</b>	<b>155</b>	<b>6839</b>